Please print or type in the unshaded areas only (fill-in areas are spaced for elite type, i.e. 12 character/inch).

DOE/RL-88-21 PUREX Plant Rev. 9, 8/4/99

A. PROCESS

FORM 3	DANGEROUS WASTE PERMIT APPLICATION    I. EPA/STATE I.D. NUMBER   W A 7 8 9 0 0 0 8 9 6 7						
FOR OFFICIAL	USE ONLY				,		
APPLICATION APPROVED	DATE RECEI\ (mo., day, & y			COMMENTS			
				Approved 08/1	19/99		
II. FIRST OR R	EVISED APPLICA	ATION					
application. If the	the appropriate bonis is your first app Section I above.	ox in A or B dication and	below (mark one box only) to indicate wh you already know your facility's EPA/ST/	ether this is the first applicati ATE I.D. Number, or if this is	ion you are submitting a revised application,	for your facility or a revised enter your facility's EPA/STATE	
A. FIRST APPL 1. E MO. 03	DAY YEAR 1943	ΓΥ (	and provide the appropriate date) 'See instructions for definition of "existing Complete Item below.) FOR EXISTING FACILITIES, PROVIDE DATE (mo., day, & yr.) OPERATION BECITHE DATE CONSTRUCTION COMMENT the boxes to the left) 'The date construction of the Hanford Fac	THE MO. DE CED (use	THE OPE	ete item below)  NEW FACILITIES, PROVIDE DATE, (mo., day, & yr.) RATION BEGAN OR IS ECTED TO BEGIN	
B. REVISED AI	PPLICATION <i>(plac</i> CILITY HAS AN II	ce an "X" be	low and complete Section I above)	ACILITY HAS A FINAL PERM	иIT		
III. PROCESS ·	- CODES AND CA	PACITIES					
codes. If me process (in:  B. PROCESS  1. AMOUN  2. UNIT Of Only the	ore lines are need cluding its design DESIGN CAPACI IT - Enter the amo F MEASURE - Foi	led, enter the capacity) in TY - For ea unt. r each amou	the list of process codes below that best of a code(s) in the space provided. If a proceed the space provided on the (Section III-C) of code entered in column A enter the case of the space provided on the (Section III-C) of the code entered in column B(1), enter the code end below should be used.  APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY	ess will be used that is not in  npacity of the process.	cluded in the list of code codes below that des	des below, then describe the	
Storage:				Treatment:			
CONTAINER TANK WASTE PILE SURFACE IN Disposal:	MPOUNDMENT	S02 S03 S04	GALLONS OR LITERS GALLONS OR LITERS CUBIC YARDS OR CUBIC METERS GALLONS OR LITERS	TANK SURFACE IMPOUNDME INCINERATOR	ENT T02 T03	GALLONS PER DAY OR LITERS PER DAY GALLONS PER DAY OR LITERS PER DAY TONS PER HOUR OR METRIC TONS PER HOUR; GALLONS PER HOUR OR LITERS PER	
LAND APPL OCEAN DISI	ICATION	D80 D81 D82 D83	GALLONS OR LITERS ACRE-FEET (the volume that would cover one acre to a depth of one foot) OR HECTARE-METER ACRES OR HECTARES GALLONS PER DAY OR LITERS PER DAY GALLONS OR LITERS	OTHER (Use for physica chemical, thermal or biol treatment processes not occurring in tanks, surfacimpoundments or inciner Describe the processes i space provided: Section	ll, T04 ogical ce ators. n the	HOUR  GALLONS PER DAY OR  LITERS PER DAY	
UNIT OF ME	ME	NIT OF ASURE CODE	UNIT OF MEASURE	UNIT OF MEASURE CODE	UNIT OF MEASURE	UNIT OF MEASURE CODE	
GALLONS G LITERS PER DAY LITERS L TONS PER HOUR CUBIC YARDS Y METRIC TONS PER HOUR CUBIC METERS C GALLONS PER HOUR GALLONS PER DAY U LITERS PER HOUR		V D W E H	ACRE-FEET HECTARE-METER ACRES HECTARES	A F B Q			

hold 200 gallons and the other can hold 400 gallons. The facility also has an incinerator that can burn up to 20 gallons per hour. B. PROCESS DESIGN CAPACITY

LINE NUMBER	CODE (from list above)	1. AMOUNT (specify)	2. UNIT OF MEASURE (enter code)	FOR OFFICIAL USE ONLY			
X-1	S02	600	G				
X-2	T03	20	E				
1	T01	392,000	V				
2	S02	1,263,233	L				
3	S06	430	С				
4							
5							
6							
7							
8							
9							
10							

C. SPACE FOR ADDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESS (CODE "T04"). FOR EACH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY.

The Plutonium-Uranium Extraction (PUREX) Plant, constructed in 1956, is located in the southeast corner of the 200 East Area. The PUREX Plant was used for the recovery of uranium and plutonium from irradiated reactor fuel. Liquid processes were used to separate the plutonium and uranium. The PUREX Plant consists of the 202-A Building and various support structures. The 202-A Building is a reinforced concrete structure 306.3 meters long, 36.3 meters wide (at its maximum), and 30.5 meters high with approximately 12.2 meters of the height below grade. The 202-A Building consists of three main structural components: (1) a thick-walled, concrete canyon containing remotely operated process equipment (in cells below grade); (2) the pipe and operating, sample, and storage galleries; and (3) an annex that included offices, process control rooms, laboratories, and building services.

TO1 and S02 are used to indicate a historical use of the tanks for storage and treatment. The tanks once used in this process have been drained and flushed and are awaiting final disposition.

SO2 reverences vessels that are permitted to store mixed waste. The PUREX Plant Vessel Table (page 6below) includes the tank identification numbers, tank locations, and tank capacities for the permitted tanks. The total process design capacity for tank storage was 1,263,233 liters.

SO6 is used to indicate a containment building subject to the requirements of 40 CFR 265, Subpart DD as prescribed in WAC-173-400 interim status facility standards. A steel open top skid containing concrete chips from the floor of E-Cell is stored in F-Cell. The solid mixed waste in the canyon could consist of contaminated discarded canyon process equipment, jumpers (or isolated components thereof) or other material from the various onsite sources.

Treatment and storage capacities are provided to reflect past operations. Current and/or future PUREX Plant activities do not propose utilization of treatment or storage capacity beyond what has been agreed to for the facility transition purposes under Section 8 of the Hanford Federal Facility Agreement and Consent Order.

PUREX Plant, Rev. 9 Page 3 of 22

### **PUREX PLANT VESSEL TABLE**

ESSEL ID	LOCATION	CAPACITY (LITERS)		
TK-D5	D Cell	19,851		
TK-E5	E Cell	19,873		
TK-E6	E Cell	19,813		
TK-F3	F Cell	19,964		
TK-F4	F Cell	19,593 1,132		
T-F5	F Cell			
E-F11	F Cell	9,804		
TK-F15	F Cell	19,419		
TK-F16	F Cell	19,870		
TK-F18	F Cell	19,798		
TK-G1	G Cell	18,662		
TK-G2	G Cell	7,064		
T-G2	G Cell	8,248		
TK-G5	G Cell	55,403		
TK-G7	G Cell	50,827		
TK-G8	G Cell	19,881		
TK-H1	H Cell	19,593		
T-H2	H Cell	7,003		
E-H4	H Cell	10,137		
TK-J1	J Cell	19,926		
TK-J3	J Cell	19,911		
T-J6	J Cell	6,057		
T-J7	J Cell	6,730		
TK-J21	J Cell	1,162		
T-J22	J Cell	568		
T-J23	J Cell	393		
TK-K1	K Cell	19,828		
T-K2	K Cell			
T-K3 K Cell		5,194		
TK-K6	K Cell	6,507		
		19,593		
T-L2 TK-L3	L Cell	447		
T-L4	L Cell	488 139		
TK-M2	M Cell	6,852		
TK-Q21	Q Cell AMU	81		
TK-Q22	Q Cell AMU	968		
TK-R1	R Cell	18,121		
TK-R2	R Cell	6,746		
T-R2	R Cell	8,282		
TK-R7	R Cell	35,174		
TK-U3	U Cell	31,124		
TK-U4	U Cell	31,184		
TK-P4	203-A	402,930		
TK-40	211-A	247,360		
TK-156	AMU	1,533		

following.

PUREX Plant, Rev. 9 Page 4 of 22

#### IV. DESCRIPTION OF DANGEROUS WASTES

A. DANGEROUS WASTE NUMBER - Enter the four digit number from Chapter 173-303 WAC for each listed dangerous waste you will handle. If you handle dangerous wastes which are not listed in Chapter 173-303 WAC, enter the four digit number(s) that describe the characteristics and/or the toxic contaminants of those dangerous wastes.

- B. ESTIMATED ANNUAL QUANTITY For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant.
- C. UNIT OF MEASURE For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

  ENGLISH UNIT OF MEASURE CODE

  METRIC UNIT OF MEASURE CODE

POUNDS P KILOGRAMS K
TONS T METRIC TONS M

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

#### D. PROCESSES

#### 1. PROCESS CODES:

For listed dangerous waste: For each listed dangerous waste entered in column A select the code(s) from the list of process codes contained in Section III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

For non-listed dangerous wastes: For each characteristic or toxic contaminant entered in Column A, select the code(s) from the list of process codes contained in Section III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed dangerous wastes that possess that characteristic or toxic contaminant.

Note: Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

NOTE: DANGEROUS WASTES DESCRIBED BY MORE THAN ONE DANGEROUS WASTE NUMBER - Dangerous wastes that can be described by more than one Waste Number shall be described on the form as follows:

- 1. Select one of the Dangerous Waste Numbers and enter it in column A. On the same line complete columns B, C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.
- 2. In column A of the next line enter the other Dangerous Waste Number that can be used to describe the waste. In column D(2) on that line enter "Included with above" and make no other entries on that line.
- 3. Repeat step 2 for each other Dangerous Waste Number that can be used to describe the dangerous waste.

EXAMPLE FOR COMPLETING SECTION IV (shown in line numbers X-1, X-2, X-3, and X-4 below) - A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

L	A. DANGEROUS		C. UNIT	D. PROCESSES				
NO E.	WASTE NO.	B. ESTIMATED ANNUAL QUANTITY OF WASTE	MEA- SURE (enter code)	1. PROCESS CODES (enter)		6	PROCESS DESCRIPTION     (if a code is not entered in D(1))	
X-1	K054	900	P	T03	D80			
X-2	D002	400	P	T03	D80			
X-3	D001	100	P	T03	D80			
X-4	D002			T03	D80			included with above
1	WT01	0	К	T01	S02			Process is not used.*
* Th	e waste codes ha	ave been listed to indicate a historic	cal use of t	anks for tr	eatment a	nd storage		
2	WT02		V	Ψ	Ψ			↓
3	WP01		<b>↓</b>	4	\			↓
4	WP02		<b>→</b>	<b>\</b>	\			Ψ
5	D001		<b>↓</b>	<b>\</b>	\			Ψ
6	D002		<b>↓</b>	4	<b>→</b>			↓
7	D003		V	Ψ	Ψ			↓
8	D004		V	Ψ	Ψ			↓
9	D005		<b>↓</b>	4	4			↓
10	D006		<b>↓</b>	4	Ψ			↓
11	D007		<b>↓</b>	4	Ψ			↓

v. FACILITY DRAWING Refer to attached drawing(s).
All existing facilities must include in the space provided on page 5 a scale drawing of the facility (see instructions for more detail).
VI. PHOTOGRAPHS Refer to attached photograph(s).

All existing facilities must include photographs (arial or ground-level) that clearly delineate all existing structures; existing storage, treatment and disposal areas; and sites

LONGITUDE (degrees, minutes, & seconds)

VII. FACILITY GEOGRAPHIC LOCATION This information is provided on the attached drawing(s) and photograph(s).

of future storage, treatment or disposal areas (see instructions for more detail).

LATITUDE (degrees, minutes, & seconds)

PUREX Plant, Rev. 9 Page 6 of 22

VIII. FACILITY OWNER						
A. If the facility owner is also the facility operator as listed in Section VII on Form 1, "General Information", place an "X" in the box to the left and skip to Section IX below.  B. If the facility owner is not the facility operator as listed in Section VII on Form 1, complete the following items:						
1. NAME OF FAC	1. NAME OF FACILITY'S LEGAL OWNER 2. PHONE NO. (area code & no.)					
3. STREET OR P.O. BOX	4. CITY OR TOWN	5. ST.	6. ZIP CODE			
IX. OWNER CERTIFICATION						
I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.						
NAME (print or type)	NAME (print or type) SIGNATURE DATE SIGNED					
Keith A. Klein, Manager U.S. Department of Energy Richland Operations Office	Keith A. Klein	08/04/1999				
X. OPERATOR CERTIFICATION						
I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.						
NAME (print or type)	SIGNATURE	DATE SIG	NED			
SEE ATTACHMENT						

PUREX Plant, Rev. 9 Page 7 of 22


#### X. OPERATOR CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

Keith A. Klein	<u>8/4/99</u>
Owner/Operator	Date
Keith A. Klein, Manager	
U.S. Department of Energy	
Richland Operations Office	
S. D. Liedle	7/21/99
Co-Operator	Date
S. D. Liedle, President	
Bechtel Hanford, Inc.	

PUREX Plant, Rev. 9 Page 8 of 22


# PUREX Plant Site Plan



E9809W

PUREX Plant, Rev. 9 Page 9 of 22


# PUREX Plant Cutaway View (202-A Building)



E9809075.2W


PUREX Plant, Rev. 9 Page 10 of 22

# 202-A Building Floor Plans



E9810002W 10/22/98 PUREX Plant, Rev. 9 Page 11 of 22

### **202-A BUILDING SECTION VIEWS**




(Not to Scale)

Note: Shaded portions denote areas that are within the TSD boundary.

E9809075.1W

PUREX Plant, Rev. 9 Page 12 of 22

# **PUREX PLANT (AERIAL VIEW)**




46°32'57" 119°31'12" 97060044-12CN (PHOTO TAKEN 1997)

PUREX Plant, Rev. 9 Page 13 of 22

## **INTERIOR CANYON**

**VIEW FROM WEST TO EAST** 



60478-4CN (PHOTO TAKEN 1973) HISTORICAL PHOTO CONSISTENT WITH CURRENT APPEARANCE PUREX Plant, Rev. 9 Page 14 of 22

# STANDARD 18,927-LITER TANK (TYPICAL OF E5, F15, F16, AND F18)




8706243-5CN (PHOTO TAKEN 1987)

PUREX Plant, Rev. 9 Page 15 of 22

## **TANK E5**


Pipe Trench Wall - Top View



46°32'57" 119°31'12" 09948-38CN (PHOTO TAKEN 1982) HISTORICAL PHOTO CONSISTENT WITH CURRENT APPEARANCE PUREX Plant, Rev. 9 Page 16 of 22

### **TANK F15 AND TANK F16**


**Pipe Trench Wall - Top View** 



46°32'57" 119°31'12" 099948 -71CN (PHOTO TAKEN 1982) HISTORICAL PHOTO CONSISTENT WITH CURRENT APPEARANCE PUREX Plant, Rev. 9 Page 17 of 22


**TANK F18** 

Pipe Trench Wall - Top View



46°32'57" 119°31'12" 099948 -74CN (PHOTO TAKEN 1982) HISTORICAL PHOTO CONSISTENT WITH CURRENT APPEARANCE PUREX Plant, Rev. 9 Page 18 of 22

# F-CELL LOOKING DOWN



99948-48CN (PHOTO TAKEN 1982)

PUREX Plant, Rev. 9 Page 19 of 22

## **E-F11 CONCENTRATOR**




8706243-8CN (PHOTO TAKEN 1987)

PUREX Plant, Rev. 9 Page 20 of 22

## **E-F11 CONCENTRATOR**

Pipe Trench Wall - Top View




46°32'57" 119°31'12" 099948-64CN (PHOTO TAKEN 1982)

PUREX Plant, Rev. 9 Page 21 of 22

**U CELL** 

Top of Tank U3 (Typical of Tank U4)



46°32'57" 119°31'12" 92102839-10CN (PHOTO TAKEN 1992) HISTORICAL PHOTO CONSISTENT WITH CURRENT APPEARANCE PUREX Plant, Rev. 9 Page 22 of 22

U CELL Tank U3 Tank U4

**Bottom of Tanks** 



46°32'57" 119°31'12" 92102839-7CN (PHOTO TAKEN 1992) HISTORICAL PHOTO CONSISTENT WITH CURRENT APPEARANCE